

This document describes the features, operational issues, and major fixes for the Pelco Sarix Professional 4 Compact cameras. Review each section to determine if an upgrade is warranted for your installation. For additional information on the camera(including the latest updates to documentation, product specifications, and software downloads), visit the Pelco Web site at www.pelco.com.

To update your camera, there are two methods and you use a different file depending on the process.

- To update your camera using the camera's web interface, use the firmware file with the .BIN extension.
- To update your camera using the Camera Configuration Tool, use the firmware file with the .FWP extension.



Note: For technical issues, contact Pelco Product Support at 1-800-289-9100 (USA and Canada) or +1-559-292-1981 (international).



Note: If your camera currently has firmware older than 5.30.0.24, please upgrade to version 5.30.0.24 before upgrading to the latest firmware version.

5.34.0.110 Release

New Features and Improvements

- Improved web interface security by adding missing X-content-type-options headers.

5.34.0.106 Release

Major Fixes

- Resolves an issue where abandoned objects could be incorrectly removed or falsely verified to brief detection gaps, improving accuracy and robustness of object detection.
- Resolved an issue where the SD card recording timestamps didn't align with the device time in the recording list, ensuring accurate playback and timeline consistency.

5.34.0.86 Release

Major Fixes

- Resolves an issue where polygon metadata was incorrectly populated.

5.34.0.36 Release

New Features and Improvements

- OpenSSL support has been updated to comply with FIPS 140-3 (level 1) standards. This update aligns with the planned upgrade of TPM on various cameras to FIPS 140-3 compliant versions, enhancing overall security.
- Added support for additional confirmation steps for the 'Restore' button and user deletion processes.

Sarix Professional 4 Compact v 5.34.0.110 Release Notes

- WebUI's Certificate Management feature has been significantly enhanced to provide a more comprehensive and user-friendly experience.
- The camera firmware now supports ONVIF SRTP integration with Milestone XProtect.

5.30.0.24 Release

New Features and Improvements

- Added a new feature with a refreshed camera WebUI, offering improved design, better streaming quality, consistent user experience.
- Added support for improved OIDs in MIBs to include Manufacturer Name, Model Number, Serial Number, and Version Number for enhanced device management.

Major Fixes

- This critical update addresses a performance issue on these cameras.
- Resolves an issue where changing object counts in analytic rules caused communication errors.

5.34.0.36 Release

New Features and Improvements

- OpenSSL support has been updated to comply with FIPS 140-3 (level 1) standards. This update aligns with the planned upgrade of TPM on various cameras to FIPS 140-3 compliant versions, enhancing overall security.
- Added support for additional confirmation steps for the 'Restore' button and user deletion processes.
- WebUI's Certificate Management feature has been significantly enhanced to provide a more comprehensive and user-friendly experience.
- The camera firmware now supports ONVIF SRTP integration with Milestone XProtect.



Pelco, Inc.
625 W. Alluvial Ave., Fresno, California 93711 United States
(800) 289-9100 Tel
(800) 289-9150 Fax
www.pelco.com

Pelco, the Pelco logo, and other trademarks associated with Pelco products referred to in this publication are trademarks of Pelco, Inc. or its affiliates. ONVIF and the ONVIF logo are trademarks of ONVIF Inc. All other product names and services are the property of their respective companies. Product specifications and availability are subject to change without notice.

© Copyright 2026, Pelco, Inc. All rights reserved.