

This document describes the features, operational issues, and major fixes for the Pelco Sarix Value 2 cameras. Review each section to determine if an upgrade is warranted for your installation. For additional information on the camera (including the latest updates to documentation, product specifications, and software downloads), visit the Pelco Web site at www.pelco.com.



Note: For technical issues, contact Pelco Product Support at 1-800-289-9100 (USA and Canada) or +1-559-292-1981 (international).



Note: Version Dependency

If your camera currently has firmware older than 2.0.1.42, please upgrade to version 2.0.1.42 before upgrading to the latest firmware version.

2.0.1.45 Release

Major Fixes

- Improved WebUI performance when TLS is enabled.
- Fixed a security flaw that allowed administrators to view other administrators' passwords.
- Resolved an issue preventing the camera from authenticating in VideoXpert.
- Fixed unintended multicast transmission from the camera that could impact network stability.

2.0.1.42 Release

Upgrade Process

1. Upgrade using the SarixValue2_2.0.1.42_a_arm.bin file. Depending on the firmware already on the camera, you may see this upgrade fail. You can ignore any failure you see during this step.
2. Upgrade to the SarixValue2_2.0.1.42_b_arm.bin file. This step should always be successful.

New Features and Improvements

- Added support for the new SRXV2-2F3-EWD-IR-ENV model camera.
- Added the ability to attach snapshots to Email notifications.
- Recordings saved to the SD Card are now named based on the times they were captured.

Major Fixes

- Fixed a problem where the Location set in the WebUI is not made accessible via the ONVIF API (and vice versa).
- Fixed a problem where analytic events could be triggered when adjusting the zoom level.
- Fixed a problem where changing the camera's name using a VMS could fail to accurately set it on the camera.
- Fixed a problem where enabling WDR through the Motorola Solutions Camera Configuration could fail to successfully enable it on the camera.

2.0.0.31 Release

New Features and Improvements

- The camera Web UI has been refreshed:

Major Fixes

- Fixed a problem where Adaptive Motion lines are not drawn on the Live View in the Web UI.
- Fixed a problem where analytics events may not be triggered in VideoXpert.
- Fixed a problem preventing users from modifying the permission level or password of a user.
- Fixed a problem where an error message could be displayed when generating a log.
- Fixed a problem where Object Leaves Area events failed to be displayed in the Events Log.

2.0.0.26 Release

New Features and Improvements

- The following new analytic behaviors have been added:
 - Object Enters Area
 - Object Leaves Area
 - Direction Violate

Major Fixes

- Fixed a problem where Sabotage Detection and Adaptive Motion events may not be received by a VMS.
- Fixed a problem where video recorded on the SD card may fail to be retrieved by a Milestone VMS.
- Users are now prevented from creating a password that includes a "Space" character.

2.0.0.18 Release

Major Fixes

- Fixed an issue where cameras could exhibit slow performance after extended use.
- Fixed an issue where firmware upgrades could fail when initiated through a VMS.



Pelco, Inc.
625 W. Alluvial Ave., Fresno, California 93711 United States
(800) 289-9100 Tel
(800) 289-9150 Fax
www.pelco.com

Pelco, the Pelco logo, and other trademarks associated with Pelco products referred to in this publication are trademarks of Pelco, Inc. or its affiliates. ONVIF and the ONVIF logo are trademarks of ONVIF Inc. All other product names and services are the property of their respective companies. Product specifications and availability are subject to change without notice.

© Copyright 2026, Pelco, Inc. All rights reserved.