

# Mount Selection Guide for Scanners and Pan/Tilts

## SCANNERS, PAN/TILTS

Scanner, Pan/Tilt Model	PM14 Wall	PM105 Wall	PSWM Wall	WM2000 Wall	WM3026 Wall	PM2010, PM2000 Pedestal	PP100 Parapet	PP200 Parapet	CM100 Corner	PA102 Pole
PS20 Series			X			X	X +			
PT270-24P	X	X								
PT280-24P	X	X								
PT570P Series				X *		X	X ❖	X ❖	X ❖	X ❖
PT680-24P				X *		X	X ❖	X ❖	X ☆	X ★
PT1250DC Series				X •	X	X	X ◇	X ◇	X *	X ❖
PT1250P Series				X •	X	X	X ◇	X ◇	X *	X ❖
PT1260EX Series				X •	X	X	X ◇	X ◇	X *	X ❖
PT1280P Series				X •	X	X	X ◇	X ◇	X *	X ❖

+ Must be used with PSWM wall mount.

\* Requires PA2000 adapter. (Use with ST1 strut if load exceeds 75 pounds [34 kg].)

❖ Must be used with WM2000 wall mount and PA2000 adapter.

☆ Must be used with WM2000 wall mount and PA2000 adapter. (Use with ST1 strut and SCM100 mount if load exceeds 75 pounds [34 kg].)

★ Must be used with WM2000 wall mount and PA2000 adapter. (Use with ST1 strut and SPA102 mount if load exceeds 75 pounds [34 kg].)

• Requires PA2010 adapter and ST1 strut.

◇ Must be used with WM2000 wall mount and PA2010 adapter.

\* Must be used with WM2000 wall mount and PA2010 adapter. (Use with ST1 strut and SCM100 mount if load exceeds 75 pounds [34 kg].)

❖ Must be used with WM2000 wall mount and PA2010 adapter. (Use with ST1 strut and SPA102 mount if load exceeds 75 pounds [34 kg].)